


TPC Wheel = 'single point ground'

Grounding principles:

- 1) define potential of both grounds same as wheel
- 2) define path of return currents via separate lines!



** redundant except when not connected to any FEEs